

Enginetech Inc
For Technical Assistance Call:
1-800-410-3664 ext 340 or ext 237

TECHNICAL BULLETIN		Mfg: CHRYSLER
	April 1998 TB 1562	Model: JEEP
		Liter: 4.0L
		V I N: S
		Year: 98-06

Replacement Connecting Rods On
1983-98 Chrysler 2.5 & 4.0L Jeep Engines

The AERA Technical Committee offers the following information on connecting rods for 1983-98 Chrysler 2.5 & 4.0L Jeep engines. A manufacturing process has been eliminated on the connecting rods for the above mentioned engines. The oil "squirt hole" passage is no longer provided on replacement rods or production engines.

This connecting rod design was first developed for older Jeep 5.9, 6.4 & 6.6L engines which required the oiling hole. It has been determined the newer 2.5 & 4.0L engines do not require this additional oiling hole. The connecting rods with or without "squirt holes" are completely interchangeable within the newer engines.

The AERA Technical Committee

This information is provided from the best available sources. However, AERA does not assume responsibility for data accuracy or consequences of its application. Members and others are not authorized to reproduce or distribute this material in any form, or issue it to their branches, divisions, or subsidiaries, etc. at a different location, without written permission.
© Copyright AERA 2006



Reference:	
-------------------	--