

Enginetech Inc
Tech Assistance 800-410-3664 ext. 340 or 237

TECHNICAL BULLETIN		Mfg: CHRYSLER
	June 2001 TB 1891	Model: CARAVAN
		Liter: 2.4L
		V I N: B
		Year: 96-06

Camshaft & Cylinder Head Caution For
1995-2001 Chrysler 2.0 & 2.4L VIN C, Y, B & X Engines

The AERA Technical Committee offers the following information regarding a camshaft & cylinder head caution on 1995-2001 Chrysler 2.0L & 2.4L VIN C, Y, B & X engines. These engines all use two camshafts (DOHC) per engine. There have been several part number suppressions already and changes may have occurred since this publication. It cannot be over emphasized how important it is to keep both camshafts with the head before and after disassembly. It is suggested to mark the components for the year and application they came out of.

NON Neon camshaft 2.4L: intake duration of 232%.324" lift & exhaust duration of 240%.256" lift looks like some 2.4L cams are cast with 532 in them and a Green color ID.

Neon camshaft 2.0L intake duration of 219.2%.344" lift & exhaust duration 219%.314" lift. The Neon 2.0L cams 0727-674 and 0777-676 both have a Red color ID ring around the middle.

Currently, there are two different head castings with the same number with a different port layout between the two heads. There are also three different pair of camshafts used that will physically fit into either heads. In some instances, technicians have not realized wrong components until bolting up manifolds or trying to start the engine.

Year	Head Casting #	Engine	Body	VIN	Car Model
1995+up	4667086	2.0L	PL	C	Neon
1995+up	4667086	2.4L	JA	X	Stratus, Breeze, Cirrus
1995+up	4667086	2.4L	JX	X	Sebring convertible
1995+up	4667086	2.4L	NS	B	Minivan

This information is provided from the best available sources. However, AERA does not assume responsibility for data accuracy or consequences of its application. Members and others are not authorized to reproduce or distribute this material in any form, or issue it to their branches, divisions, or subsidiaries, etc. at a different location, without written permission.
© Copyright AERA 2006



Reference:	
-------------------	--

TECHNICAL BULLETIN			Mfg:	CHRYSLER
			Model:	CARAVAN
			Liter:	2.4L
			V I N:	B
June 2001 TB 1891			Year:	96-06

1995+up 4667867 2.0L FJ Y Avenger, Sebring
Sebring Coupe & Eagle Talon
1995+up Camshafts 2.0L PL Neon
Intake 4667917 superceded to 4777631AA
Exhaust 4667918 superceded to 4777632AA

1995+up Camshafts 2.4L JA Stratus, Breeze, Cirrus
JX Sebring convertible
NS MiniVan
Intake 4621533 superceded to 4777638AA
Exhaust 4621535 superceded to 4777637AA
Caution: Uses valve spring part number 4621530

1995+up 2.0L FJ Avenger, Sebring Coupe, Eagle Talon
Intake 4667673 superceded to 4777629AA
Exhaust 4667675 superceded to 4777630AA
Caution: Uses valve spring part number 4777555

The AERA Technical Committee

This information is provided from the best available sources. However, AERA does not assume responsibility for data accuracy or consequences of its application. Members and others are not authorized to reproduce or distribute this material in any form, or issue it to their branches, divisions, or subsidiaries, etc. at a different location, without written permission.
© Copyright AERA 2006



Reference:	
-------------------	--